

State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT



Michael O. Leavitt Governor Lowell P. Braxton

Division Director

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801

801-538-5340 801-359-3940 (Fax)

801-538-7223 (TDD)

Partial: XXX Complete: Exploration: Inspection Date & Time: 10/28/99 / 10:00a.m.-2:00p.m.

Date of Last Inspection: 9/29/99

| Mine Name: Wellington Preparation Plant County: Carbon Permit Number: ACT/007/012 | | | | | | |
|---|--|--|--|--|--|--|
| Permittee and/or Operator's Name: Nevada Electric Investment Company (NEICO) | | | | | | |
| Business Address: c/o Mt. Nebo Scientific, P.O. Box 337, Springville, Utah 84663 | | | | | | |
| Type of Mining Activity: Underground Surface Prep. Plant XXX Other | | | | | | |
| Company Official(s): Patrick Collins, Vicky Miller | | | | | | |
| State Officials(s): Stephen J. Demczak Federal Official(s): None | | | | | | |
| Weather Conditions: Sunny, 50's 20'3 | | | | | | |
| Weather Conditions: Sunny, 50's Existing Acreage: Permitted-1720 Disturbed-356 Regraded-1.5 Seeded-1.5 Bonded-744 | | | | | | |
| Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded | | | | | | |
| Status: _Exploration/_XXX_Active/Inactive/Temporary Cessation/Bond Forfeiture | | | | | | |
| Reclamation (_Phase I/_Phase II/_Final Bond Release/_LiabilityYear) | | | | | | |

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

| 1. 2. 3. 4. | PERMITS, CHANGE, TRANSFER, RENEWAL, SALE SIGNS AND MARKERS TOPSOIL | EVALUATED [XX] [XX] | <u>N/A</u> | COMMENTS [] [XX] [] | NOV/ENI |
|--|---|----------------------|------------|-----------------------------|---------|
| a. b. c. d. | HYDROLOGIC BALANCE: DIVERSIONS SEDIMENT PONDS AND IMPOUNDMENTS OTHER SEDIMENT CONTROL MEASURES WATER MONITORING EFFLUENT LIMITATIONS | [XX] [XX] [XX] | | [XX] [XX] [XX] [_] | |
| 5. 6. 7. 8. | EXPLOSIVES DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS NONCOAL WASTE PROTECTION OF FISH, WILDLIFE AND | | | | |
| 10. 11. 12. 13. 14. 15. | RELATED ENVIRONMENTAL VALUES SLIDES AND OTHER DAMAGE CONTEMPORANEOUS RECLAMATION BACKFILLING AND GRADING REVEGETATION SUBSIDENCE CONTROL CESSATION OF OPERATIONS ROADS: | | | | |
| a. | | | | | |

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/012

DATE OF INSPECTION: 10/28/99

(Comments are Numbered to Correspond with Topics Listed Above)

2. SIGNS AND MARKERS -

The identification signs were inspected and were found to be complete and accurate. The phone number needs to be more visible due to fading.

The topsoil signs were located on the topsoil piles as required.

4A. DIVERSIONS -

The diversions were spot-checked throughout the property and would function properly in an event.

4B. SEDIMENT PONDS -

Sediment ponds were inspected and no hazardous conditions were noticed. None of the sediment ponds were discharging during the inspection.

4C. OTHER SEDIMENT CONTROL AREAS -

Several alternate sediment control areas were inspected and were found to comply with the R645 Coal Rules. Silt fences have recently been repaired.

8. NON-COAL WASTE -

Several 55-gallon drums are located near the undisturbed area by the course refuse pile; these drums need to be stored near the sediment pond. The containers were full of petroleum liquid. If ruptured, the fluid would flow into the pond; where it should flow. Permittee has committed to move these containers.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Mt. Nebo Scientific Henry Austin (OSM)
Given to: Pam Grubaugh-Littig (DOGM)
Filed to: Price Field Office

Date: November 2, 1999

Inspector's Signature: #39

Stephen J. Demczak